RISO, INC. TECHNICAL INFORMATION BULLETIN

Subject: Master Removal Sensor Bulletin No.: 82

[ ] Factory Modification	Applies to:	Modification Schedule:	Factory Installed _____
[ ] Field Modification			
[ ] Safety Information	RC Series	[ ] TBS	Field Installed _____
[x] Technical Information		[ ] Next Call	
[ ] General Information		[ ] Next PM	Fitting Time _____
[ ] Adv. Tech Information		[x] As Necessary	

To prevent the Master Removal Sensor (Receive) from being smudged by ink, causing a Master Jam Detection at the entrance of the Disposal Box, both the Sensor and Bracket have been modified.

This is an arbitrary modification and should only be considered on systems that have frequent misdetection of used master material in the disposal process. If it is determined that either Sensor (Send or Receive) requires replacement, both should be changed to the newer type.

Normally, the Sensor Bracket would not have to be changed, however, keep in mind that the new style Bracket will only accept the modified Master Removal Sensor Receive.

PART NUMBER	DESCRIPTION
011-60033-203	Master Removal Sensor (Send)
011-60034-307	Master Removal Sensor (Receive)
011-14446-005	Bracket II; M.Rmv. Sensor (Rcv.)

Serial Number cut-in

RC4500	#94410013
RC5600	#91514073
RC5800	#92451397